

Work Order ID 78145

December-29-11 9:56:52 AM

78145

Page 1

Item ID: D2856-400-694

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Abrasion Strip

Start Date: 29/12/2011 Start Qty: 12.00

12

Cust Item ID:

Required Date: 03/01/2012 Req'd Qty: 12.00

12

Customer:

Reference:

Approvals: Process Plan: M.L.J

Date: 11/12/29

Tooling:

Date:

Run Start ***NR1***

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2856-	Rev A								
100		0.00							
100	Small Fab								
Packaging	Memo	0.00							
Packaging	Cut as per dwg D2856								
110	QC6- Inspect dimensions to drawing	0.00							
110									
QC	Memo	0.00							
Quality Control									
120	Identify as per dwg & Stock Location: <u>409</u>	0.00							
120									
Packaging	Memo	0.00							
Packaging									

12/01/11 (12)

SB 12/01/11

(12)

12/1/12 (12)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 78145***78145***

Page 2

December-29-11 9:56:52 AM

Item ID: D2856-400-694

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Abrasion Strip

Start Date: 29/12/2011 Start Qty: 12.00

12

Cust Item ID:

Required Date: 03/01/2012 Req'd Qty: 12.00

12

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00


130

QC

Memo

0.00

Quality Control

12/11/12 
ME
12-01-12

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

December-29-11 9:56:56 AM

Page 1

Work Order ID: 78145

78145

Parent Item: D2856-400-694

D2856-400-694

Parent Item Name: Abrasion Strip

Start Date: 29/12/2011

Required Date: 03/01/2012

Start Qty: 12.00

Required Qty: 12.00

Comments: IPP Rev:A 10.11.02 as per revA DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2856-400		Manufactured	No			100	f	200.2721	0.5783	7.304842			

D2856-400

Abrasion Strip

**

Handwritten signature and date 12/01/11

Location

Loc Qty

Loc Code

ST409

200.2721

63735

0.6696

68076

0.3149

71164

21.66

73491

177.6276

7.304842

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



DESIGN <i>CP</i>	DRAWN BY <i>CP</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>A</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2856	REV. A SHEET 1 OF 1
DATE 00.11.17		TITLE ABRASION STRIP	SCALE NTS
A	00.11.17	NEW ISSUE	

RELEASED
00.11.17

SPECIFICATION CONTROL DRAWING



MATERIAL: OUTDOOR GRADE POLYURETHANE PROTECTIVE TAPE
3M, P/N 8681 (OR 8681HS)
THICKNESS: 0.012"

SPECIFICATION: D2856-XXX-YYY ABRASION STRIP

WIDTH
LENGTH

EG: 1.75"x2.50" ABRASION STRIP = D2856-175-250

TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 78145 M.C.J.
11/12/29

Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries